



# Patchwork Triangle Box

By Janet Wilhelm for Walnut Hollow®

## Materials:

- [Walnut Hollow® #28013 Mini Tool Set](#)
- [Walnut Hollow® Metal Roll, Copper](#)
- [Walnut Hollow® #28016 Metal Tape](#)
- [Walnut Hollow® #27777 Hinged Box – Small](#)
- Other Supplies: Metal ruler, paper towel, sandpaper, scissors, sponge brush, spray varnish, wood stain

## Instructions:

Note: Foam mat, Handle, Points and Rollers used below are included in the Mini Tool Set.

1. To prepare box for staining, use sandpaper to lightly sand to a smooth finish. Remove dust with paper towel. Use sponge brush to apply wood stain to entire wood surface. Use as directed on container. Let dry. Apply 2-3 coats of spray varnish.
2. Use scissors to cut a 3" x 4 ½" piece of Copper Metal for top of box Place metal on Foam Mat. Attach Medium Roller onto Handle. Referring to photo, use Medium Roller to create a ¼" design around entire edge of metal. Use metal ruler as a guide to insure straight lines. Attach Narrow Roller onto Handle. Use Narrow Roller to create a line inside of Medium Roller design. Remove Narrow and Medium Rollers from Handle. Attach Large Ball and Cup onto Handle. Create dots horizontally across top and bottom of box. Turn metal over and press large Ball ½" apart. Turn metal over and press large Cup on top of each dot. When finished remove Large Ball and Cup from Handle.
3. Attach Narrow Roller to Handle. Use Narrow Roller to create a thin line inside of each row of dots. Use Narrow Roller to create triangle shapes in center of metal. Use a variety of Rollers and Points to create different designs in each triangle. Make some designs on front of metal and some designs on back of metal for added variety.
4. Adhere metal to box with Metal Tape. Use scissors to cut Tape to fit on back of metal and press in place. Remove backing from Tape and press metal onto top of box.



WALNUT HOLLOW