



Wood Carved Leaf Box

Materials:

- [Walnut Hollow® #17020P Candle Box](#)
- [Walnut Hollow® #4004 Carving Set-4 Pieces](#)
- Other Supplies: gold metallic paint, dark green paint, paper towel, paint brush, pencil, sandpaper, spray varnish

Instructions:

1. To prepare wood for painting, use sandpaper to lightly sand entire wood surface. Remove dust with paper towel.
2. Use pencil to draw leaves in a random pattern on top and sides of box. Draw free hand, use a stencil, or trace a real or silk leaf.
3. Use brush to paint each leaf dark green.
4. Use gouges to carve grooves in the wood except for the leaves.
5. Use small gouge to carve veins in each leaf.
6. Use brush to paint entire box with gold metallic paint. The dark green will show through the metallic gold paint. Let dry.
7. Apply 2-3 coats of spray varnish for a protective finish.

