

# WALNUT HOLLOW® HOT TOOL POINTS

Points can be used with  
ALL Walnut Hollow® Hot Tools.



**5590**  
**Universal Point**  
Performs all fundamental wood burning techniques.



**5591**  
**Mini Universal Point**  
Smaller version of the Universal Point (5590). Performs all fundamental wood burning techniques. Best for very fine and controlled lines.



**5592**  
**Flow Point**  
Use to burn curves, dots, and fine details. Works well for cursive writing and dot shading techniques.



**5593**  
**Mini Flow Point**  
Use to burn small and intricate dots, circles, and cursive writing.



**5594**  
**Shading Point**  
Creates smooth, even shading in subtle gradations or dark, bold shading. Use different pressure, speed, and movement for contrasting looks. Leaf shapes are easy to stamp using the shape of the point.



**41765**  
**Transfer Point**  
Transfers photocopies of black & white and color laser images onto surfaces. Circle shapes are easy to stamp using the shape of the point.



**5595**  
**Texture 'n' Tone Point**  
Use to burn several fine, textured lines with one stroke.




**5596**  
**Cone Point**  
Use to burn fine lines, dots, and curves.



**5598**  
**Calligraphy Point**  
Creates basic calligraphy style lettering and shaping.



**24589**  
**Tapered Point**  
Cuts intricate designs from stencil material and burns extra-fine, detailed lines.



**25651**  
**Hot Knife Point**  
Cuts and shapes a variety of materials such as foam, faux pumpkins, foam core board, and wax.



**25683**  
**Lead-Free Solder**  
Use to join metal together. 99.25% Tin, .75% Copper with rosin core. No additional flux required.